MANUFACTURING SAFETY ALERT

Ask Yourself "Could it happen here?"

DESCRIPTION OF EVENT

Loader Incident

During a routine operator switchover, smoke was spotted coming from the engine bay of a 624K Loader. When the relief operator opened the compartment panel, they found smoke and glowing embers around and beneath the engine.

Operators in the area quickly responded using a fire extinguisher and hose to extinguish the embers and clear out built-up wood fiber and dust. Thanks to their fast response, they prevented a potentially serious fire.

Equipment in this area is regularly exposed to to high levels of wood fiber and dust, which can quickly build up—especially in engine compartments—and pose a significant fire risk if not cleaned regularly.

SUGGESTED ACTIONS

- Clean wood dust and fibre thoroughly every day and night.
- Pay extra attention to high-risk areas like engine compartments, electrical panels and hot surfaces.
- Operators should keep a close eye out during inspections and cleaning routines for accumulated wood fibre and dust.



MOST IMPORTANT TAKE AWAY

Regular maintenance and housekeeping are essential to reducing fire risk.

Consider performing engine blowdowns every four (4) hours to prevent build-up.

The BCFSC and WPAC would like to thank the company that submitted the incident for this safety alert.

BCFSC welcomes all incident and nearmiss submissions from all sectors of the forest industry.





BCFSC welcomes all incident or near-miss submissions. To protect your privacy, we will review and remove all identifying information.

Scan the QR Code
with your mobile
device's camera to
access this alert.

