FOREST INDUSTRY SAFETY ALERT
Close Call

Location: G.T.
Road 22 km

Date of Incident:
Dec. 19 2008

Details of Incident:
On Dec. 19 a buncher operator was driving a D.N.T. pickup home after his shift. The road conditions were compact snow and slippery. At 22km on the G.T. road, he slid of the road and ended up in the ditch. He needed to be pulled out with another pickup, and after pulling the pickup out they looked the pickup over and there was no damage. He proceeded home.

Root Cause:

- Driving too fast for road conditions.
- In too much of a hurry.

Recommended Preventative Actions:

- Slow down, always drive to road conditions.
- Always be alert while driving.

For more information, please call:
Clint Ludwig at D.N.T. shop @ 250-567-5167