LONG SHOT HOLDINGS LTD SAFETY ALERT

Copy To: Employees & Contractors Date: April 17, 2009

Subject: Runaway Log File: 019

DETAILS OF INCIDENT: On February 19, 2009 a logging crew which entailed a loader operator, yarding crew and bucker man were working closely together. The yarder was yarding downhill with the grapple at the back end pulling down by the top; when a 10 ft slag came out of the grapple which tumbled down the hill. At this time the loader operator and his bucker were working on a skid at the bottom, in the line of fire of this runaway log. The yarder operator sounded off his horn just in time for the bucker to run into the safe zone. The runaway log crashed into the skid that the bucker was working on at the time.

INVESTIGATION: The area that the workers were at was very steep ground and the weather conditions were wet with snow mixed in making the ground unstable. The work site was stopped immediately and all workers were evacuated from the area.

RECOMMENDED PREVENTATIVE ACTIONS: Once it was safe to do so the supervisor assessed the area and it was decided that only the yarding would commence and once the yarder was finished with this specific area then the ground crew could come back and work. The supervisor monitored the area closely to ensure the safety of all workers.

Please review this close call/hazard alert with all workers so they understand the precautions they must take while working for Long Shot Holdings Ltd.

Reported by: Laura Olynyk **Safety Coordinator**