FOREST INDUSTRY SAFETY ALERT
Close Call

Location:
12.5km Ocock F.S.R**.**

Date of Incident:
February 13 2009

Details of Incident:
A DNT truck came onto the Ocock road, loaded at 17km. The trucker was calling his miles, but when he came to 12.5km he met an empty truck, on a corner, that was on the wrong channel. The DNT trucker was forced to swerve, causing his trailer to slide through the snow bank. No one went into the ditch and no one got hurt.

Root Cause:
- Empty truck was on the wrong channel

Recommended Preventative Actions:
- Reminded truckers to drive with caution.
- Don't assume everyone can hear you, and that everyone has a radio.

For more information, please call:
Clint Ludwig @ 250-567-5167