BC **Forest Safety** Council
Unsafe is Unacceptable

Forest Industry Safety Alert

Close Call or Serious Incident: Close Call

Select distribution (*internal or external*): External - Share with SAFE Companies

Safety Alert type: Manufacturing

BCTS Business Area: TCC - Cariboo-Chilcotin Timber Sales Office - Williams Lake, Quesnel

Date of Incident: Dec 1, 2009

Company Name (optional): Pinnacle Pellet

Details of Incident

A 950 loader was operating close to a operating wood grinder and a piece of tramp metal flew out of the grinder and struck the loader breaking the window in the access door.

Recommended Preventative Actions:

All operations should review the location of their grinders and ensure that they are away from traffic areas and workers avoid being in proximity when they are running.

For more information please contact:

Lorne Davies