



Forest Industry Safety Alert

Close Call or Serious Incident

Close Call

Select distribution (*internal or external*):

External - Share with SAFE Companies

Safety Alert type:

Manufacturing

BCTS Business Area

TCC - Cariboo-Chilcotin Timber Sales Office - Williams Lake, Quesnel

Date of Incident

Company Name (optional)

Dec 1, 2009

Pinnacle Pellet

Details of Incident

A 950 loader was operating close to a operating wood grinder and a piece of tramp metal flew out of the grinder and struck the loader breaking the window in the access door.

Recommended Preventative Actions:

All operations should review the location of their grinders and ensure that they are away from traffic areas and workers avoid being in proximity when they are running.

For more information please contact:

Lorne Davies