



**INTERFOR**<sup>®</sup>

Date: July 20, 2016

# SAFETY ALERT

## New Scale Safety Procedures

**Location:** Grand Forks Sawmill



**Summary:** A driver left the scales without following correct procedures, putting a Weighmaster at risk. Drivers must not get in their cabs when a worker is on the scales.

**NEW PROCEDURES:** A cone will be placed outside of driver's door upon arrival. Driver may not move the cone or leave the scales until the Weighmaster/Scaler determines the area is clear and removes the cone.



For more information on this alert, please contact: J. Walker Scaling Ltd.  
(250-574-0802) or Ron Last (778-206-4082)