

MANUFACTURING SAFETY ALERT

Ask Yourself
“Could it happen here?”

DESCRIPTION OF EVENT

Forklift Spray Paint Can

A forklift was driving through the rough yard and went over a bump. A spray paint can was stored on the air ride seat. The air ride seat bounced when going over bump and punctured the incorrectly stored spray paint can. Paint sprayed on floor of cab and on operator's pant legs.



SUGGESTED RECOMMENDATIONS:

- Pre-trip inspection form should specifically include loose objects in cab.
- Supervisors must audit periodically to ensure compliance.

MOST IMPORTANT TAKE AWAY

Avoid carrying loose items and correctly secure all items in your forklift cab.

MAG
Manufacturing Advisory Group



BCFSC welcomes all incident or near-miss submissions. To protect your privacy, we will review and remove all identifying information.

To share an incident or to subscribe to the Safety Alert of the Week, visit: www.bcfscsafe.org/safety-alerts/

Scan the QR Code
with your mobile
device's camera to
access this alert.

